



Beaufort County
Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Donaldson Camp Road

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Project improved 116 L.F. of drainage system. Repaired sinkhole. Cleaned out (2) catch basins. Jetted (1) crossline pipe, 100 L.F. of roadside pipe and 16 L.F. of outfall pipe.

Completion: Mar-13

2013-613 / Donaldson Camp Road	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Cost	Total Cost
AUDIT / Audit Project	0.5	\$10.45	\$0.00	\$0.00	\$0.00	\$6.62	\$17.06
CBCO / Catch basin - clean out	16.0	\$377.84	\$189.34	\$31.69	\$0.00	\$259.76	\$858.63
HAUL / Hauling	6.0	\$131.10	\$64.20	\$31.41	\$0.00	\$82.10	\$308.81
ONJV / Onsite Job Visit	4.0	\$111.66	\$16.08	\$12.48	\$0.00	\$85.40	\$225.62
SR / Sinkhole repair	12.0	\$266.76	\$48.55	\$24.43	\$0.00	\$128.48	\$468.22
2013-613 / Donaldson Camp Road Sub Total	48.5	\$1,133.96	\$428.97	\$146.19	\$0.00	\$724.71	\$2,433.82
Grand Total	48.5	\$1,133.96	\$428.97	\$146.19	\$0.00	\$724.71	\$2,433.82

Before



After



**Project: Donaldson
Camp Road**

**Activity: Routine/
Preventive
Maintenance**
















**Project #:
2013-613**


**Township: Port
Royal Island**

**Completed:
March 2013**

Legend

TYPE

-  River
-  Creek/Stream
-  River/Creek/Marsh BANK
-  Channel (fka Outfall)
-  Channel Pipe
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Access Pipe
-  Bleeder Pipe
-  Parcels



1 inch = 90 feet