



**Beaufort County**  
**Public Works**  
**Stormwater Infrastructure**  
*Project Summary*

**Project Summary:** Mallard Lane

**Activity:** Routine/Preventive Maintenance

**Narrative Description of Project:**

Project improved 115 L.F. of drainage system. Cleaned out 115 L.F. of outfall ditch.

**Completion:** Mar-13

<b>2013-572 / Mallard Lane</b>	<b>Labor Hours</b>	<b>Labor Cost</b>	<b>Equipment Cost</b>	<b>Material Cost</b>	<b>Contractor Cost</b>	<b>Indirect Labor</b>	<b>Total Cost</b>
AUDIT / Audit Project	0.5	\$10.45	\$0.00	\$0.00	\$0.00	\$6.62	\$17.06
HAUL / Hauling	5.0	\$109.25	\$53.50	\$17.45	\$0.00	\$61.05	\$241.25
ODCO / Outfall ditch - cleaned out	12.0	\$266.76	\$65.25	\$24.43	\$0.00	\$128.48	\$484.92
PRRECON / Project Reconnaissance	3.5	\$140.81	\$14.07	\$15.60	\$0.00	\$118.86	\$289.34
<b>2013-572 / Mallard Lane</b>	<b>21.0</b>	<b>\$527.26</b>	<b>\$132.82</b>	<b>\$57.48</b>	<b>\$0.00</b>	<b>\$315.01</b>	<b>\$1,032.57</b>
<b>Sub Total</b>							
<b>Grand Total</b>	<b>21.0</b>	<b>\$527.26</b>	<b>\$132.82</b>	<b>\$57.48</b>	<b>\$0.00</b>	<b>\$315.01</b>	<b>\$1,032.57</b>

Before



After





**Project: Mallard Lane**

**Activity: Routine/  
Preventive  
Maintenance**

**Project #:  
2013-572**
















**Township: Port  
Royal Island**

**Completed:  
March 2013**



**Legend**

**TYPE**

-  River
-  Creek/Stream
-  River/Creek/Marsh BANK
-  Channel (fka Outfall)
-  Channel Pipe
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Access Pipe
-  Bleeder Pipe
-  Parcels



**1 inch = 50 feet**