

Project Summary

Project Summary: Sanders/St. Helena Island Post Office Outfall

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Completion: Mar-13

Project improved 250 L.F. of drainage system. Cleaned out 250 L.F. of channel. Repaired (1) manhole lid. Installed rip rap on backslope for erosion control.

2013-008A / Sanders/ St. Helena Island Post Office Outfall	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.45	\$0.00	\$0.00	\$0.00	\$6.62	\$17.06
CBREP / Catch basin - repaired	10.0	\$208.70	\$20.10	\$29.50	\$0.00	\$132.30	\$390.60
ERCON / Erosion control	14.0	\$319.79	\$98.90	\$403.11	\$0.00	\$207.46	\$1,029.26
HAUL / Hauling	21.0	\$458.85	\$298.30	\$1,177.09	\$0.00	\$302.82	\$2,237.06
ODCO / Outfall ditch - cleaned out	40.0	\$899.60	\$316.80	\$410.71	\$0.00	\$567.90	\$2,195.01
ONJV / Onsite Job Visit	11.0	\$364.43	\$44.22	\$31.20	\$0.00	\$294.91	\$734.76
2013-008A / Sanders/ St. Helena Island Post Office Outfall	96.5	\$2,261.82	\$778.32	\$2,051.60	\$0.00	\$1,512.00	\$6,603.74
Grand Total	96.5	\$2,261.82	\$778.32	\$2,051.60	\$0.00	\$1,512.00	\$6,603.74







