



# Beaufort County Public Works Stormwater Infrastructure Project Summary

**Project Summary:** Shelter Church Road

**Activity:** Routine/Preventive Maintenance

**Narrative Description of Project:**

Project improved 628 L.F. of drainage system. Cleaned out 618 L.F. of roadside ditch. Installed 10 L.F. of roadside pipe and rip rap for erosion control.

**Completion:** Mar-13

2013-676 / Shelter Church Road	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.45	\$0.00	\$0.00	\$0.00	\$6.62	\$17.06
HAUL / Hauling	20.0	\$437.00	\$214.00	\$278.32	\$0.00	\$288.40	\$1,217.72
ONJV / Onsite Job Visit	7.0	\$49.22	\$28.14	\$31.20	\$0.00	\$158.81	\$267.37
RSDCL / Roadside Ditch - Cleanout	75.0	\$1,708.65	\$447.12	\$246.22	\$0.00	\$1,150.65	\$3,552.64
<b>2013-676 / Shelter Church Road Sub Total</b>	<b>102.5</b>	<b>\$2,205.32</b>	<b>\$689.26</b>	<b>\$555.74</b>	<b>\$0.00</b>	<b>\$1,604.48</b>	<b>\$5,054.79</b>
<b>Grand Total</b>	<b>102.5</b>	<b>\$2,205.32</b>	<b>\$689.26</b>	<b>\$555.74</b>	<b>\$0.00</b>	<b>\$1,604.48</b>	<b>\$5,054.79</b>

Before



During



After



**Project: Shelter Church Road**

**Activity: Routine/ Preventive Maintenance**
















**Project #: 2013-676**

**Township: Port Royal Island**

**Completed: March 2013**

**Legend**

**TYPE**

-  River
-  Creek/Stream
-  River/Creek/Marsh BANK
-  Channel (fka Outfall)
-  Channel Pipe
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Access Pipe
-  Bleeder Pipe
-  Parcels

Cleaned out 618 LF of roadside ditch. Installed 10 LF of roadside pipe and rip rap for erosion control.



**SHELTER CHURCH RD**

**D/W**

**TRASK PKWY**



**1 inch = 77 feet**