



Beaufort County Public Works Stormwater Infrastructure Project Summary

Project Summary: Wimbee Landing Road

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Project improved 800 L.F. of drainage system. Cleaned out 800 L.F. of outfall ditch.

Completion: Mar-13

2013-607 / Wimbee Landing Road	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.45	\$0.00	\$0.00	\$0.00	\$6.62	\$17.06
HAUL / Hauling	19.5	\$426.08	\$208.65	\$125.64	\$0.00	\$248.04	\$1,008.41
ODCO / Outfall ditch - cleaned out	17.0	\$413.91	\$225.14	\$48.12	\$0.00	\$228.52	\$915.69
ONJV / Onsite Job Visit	1.0	\$20.48	\$4.02	\$3.12	\$0.00	\$18.23	\$45.85
RSDCL / Roadside Ditch - Cleanout	30.0	\$666.90	\$197.80	\$52.35	\$0.00	\$321.20	\$1,238.25
STBY / Stand By	10.0	\$236.15	\$110.80	\$26.18	\$0.00	\$162.35	\$535.48
2013-607 / Wimbee Landing Road	78.0	\$1,773.96	\$746.41	\$255.41	\$0.00	\$984.96	\$3,760.73
Grand Total	78.0	\$1,773.96	\$746.41	\$255.41	\$0.00	\$984.96	\$3,760.73

Before



During



After



Project: Wimbee Landing Road

Activity: Routine/ Preventive Maintenance
















Project #: 2013-607


Township: Sheldon

Completed: March 2013

Legend

TYPE

-  River
-  Creek/Stream
-  River/Creek/Marsh BANK
-  Channel (fka Outfall)
-  Channel Pipe
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Access Pipe
-  Bleeder Pipe
-  Parcels



Cleaned out 800 LF of outfall ditch.



1 inch = 599 feet