



Beaufort County Public Works Stormwater Infrastructure Project Summary

Project Summary: Smalls Hill Road

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Completion: May-13


Project improved 240 L.F. of drainage system. Cleaned out 240 L.F. of roadside ditch.

2013-647 / Smalls Hill Road	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.45	\$0.00	\$0.00	\$0.00	\$6.62	\$17.06
HAUL / Hauling	5.0	\$109.25	\$53.50	\$19.50	\$0.00	\$72.10	\$254.35
RSDCL / Roadside Ditch - Cleanout	10.0	\$224.20	\$69.27	\$22.38	\$0.00	\$149.55	\$465.40
2013-647 / Smalls Hill Road	15.5	\$343.90	\$122.77	\$41.88	\$0.00	\$228.26	\$736.81
Sub Total							
Grand Total	15.5	\$343.90	\$122.77	\$41.88	\$0.00	\$228.26	\$736.81

Before



During



After




Project: Smalls Hill Road

**Activity: Routine/
Preventive
Maintenance**

**Project #:
2013-647**

**Township: Port
Royal Island**

**Completed:
June 2013**



Legend	
TYPE	
	River
	Creek/Stream
	River/Creek/Marsh BANK
	Channel (fka Outfall)
	Channel Pipe
	Lateral
	Lateral Pipe
	Roadside
	Roadside Pipe
	Road Pipe
	Crossline Pipe
	Driveway Pipe
	Access Pipe
	Bleeder Pipe



1 inch = 105 feet