



Beaufort County Public Works Stormwater Infrastructure Project Summary

Project Summary: George Williams Lane

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Replaced (1) driveway pipe.

Completion: Nov-13

2014-537 / George Williams Lane	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
DPRPL / Driveway Pipe - Replaced	12.0	\$283.06	\$94.00	\$238.36	\$0.00	\$106.68	\$722.11
HAUL / Hauling	4.0	\$84.84	\$42.80	\$179.78	\$0.00	\$57.68	\$365.10
ONJV / Onsite Job Visit	5.0	\$149.20	\$18.10	\$14.85	\$0.00	\$91.15	\$273.30
PRRECON / Project Reconnaissance	2.0	\$66.36	\$7.24	\$8.91	\$0.00	\$48.94	\$131.45
UTLOC / Utility locates	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
2014-537 / George Williams Lane Sub Total	24.0	\$603.92	\$162.14	\$441.90	\$0.00	\$317.68	\$1,525.64
Grand Total	24.0	\$603.92	\$162.14	\$441.90	\$0.00	\$317.68	\$1,525.64

Before



During



After



Project: George Williams Lane

Activity: Routine/ Preventive Maintenance















Project #: 2014-537

Township: Sheldon

Completed: October 2013

Legend

TYPE

-  River
-  Creek/Stream
-  River/Creek/Marsh BANK
-  Channel (fka Outfall)
-  Channel Pipe
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Access Pipe
-  Bleeder Pipe



1 inch = 99 feet