**Beaufort County Public Works** Stormwater Infrastructure

Project Summary

Project Summary: Ardmore Avenue

## Activity: Routine/Preventive Maintenance

## Narrative Description of Project:

Project improved 200 L.F. of drainage system. Repaired sinkhole. Cleaned out (1) catch basin. Jetted (1) crossline pipe, (1) driveway pipe and 200 L.F. of roadside pipe.

2013-642 / Ardmore Avenue	Labor	Labor	Equipment	Material	Contractor	Indirect	
	Hours	Cost	Cost	Cost	Cost	Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
DPREM / Driveway Pipe - Removed	24.0	\$539.88	\$45.59	\$36.70	\$0.00	\$361.44	\$983.62
HAUL / Hauling	13.5	\$289.91	\$144.45	\$54.10	\$0.00	\$194.67	\$683.13
ONJV / Onsite Job Visit	2.0	\$66.36	\$7.24	\$8.91	\$0.00	\$48.94	\$131.45
PRRECON / Project Reconnaissance	5.0	\$137.61	\$19.30	\$32.67	\$0.00	\$98.35	\$287.93
RSPJ / Roadside Pipe - Jetted	10.0	\$239.76	\$110.80	\$78.46	\$0.00	\$164.70	\$593.72
SR / Sinkhole repair	20.0	\$445.56	\$18.10	\$20.58	\$0.00	\$298.00	\$782.24
2013-642 / Ardmore Avenue	75.0	\$1,729.31	\$345.48	\$231.42	\$0.00	\$1,172.71	\$3,478.92
Sub Total							
Grand Total	75.0	\$1,729.31	\$345.48	\$231.42	\$0.00	\$1,172.71	\$3,478.92

Before








After



Completion: Oct-13



1 inch = 83 feet

Feet

Date Print: 11/21/13 File:C:/sethdata/projects/projectmaps/Ardmore Ave 2013-642