



# Beaufort County Public Works Stormwater Infrastructure Project Summary

**Project Summary:** Benton Field Road

**Activity:** Routine/Preventive Maintenance

**Narrative Description of Project:**

**Completion:** Oct-13

Project improved 1,154 L.F. of drainage system. Cleaned out 1,154 L.F. of roadside ditch. Jetted (2) crossline pipes and (4) driveway pipes.

2014-514 / Benton Field Road	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
HAUL / Hauling	30.0	\$648.90	\$321.00	\$144.06	\$0.00	\$432.60	\$1,546.56
ONJV / Onsite Job Visit	6.0	\$199.08	\$21.72	\$29.70	\$0.00	\$146.82	\$397.32
RSDCL / Roadside Ditch - Cleanout	60.0	\$1,349.71	\$188.81	\$104.65	\$0.00	\$903.60	\$2,546.77
STBY / Stand By	10.0	\$214.20	\$107.00	\$68.60	\$0.00	\$144.20	\$534.00
<b>2014-514 / Benton Field Road Sub Total</b>	<b>106.5</b>	<b>\$2,422.12</b>	<b>\$638.53</b>	<b>\$347.01</b>	<b>\$0.00</b>	<b>\$1,633.84</b>	<b>\$5,041.50</b>
<b>Grand Total</b>	<b>106.5</b>	<b>\$2,422.12</b>	<b>\$638.53</b>	<b>\$347.01</b>	<b>\$0.00</b>	<b>\$1,633.84</b>	<b>\$5,041.50</b>

Before



During



After



**Project: Benton Field Road**

**Activity: Routine/ Preventive Maintenance**















**Project #: 2014-514**


**Township: Bluffton**

**Completed: October 2013**

**Legend**

**TYPE**

-  River
-  Creek/Stream
-  River/Creek/Marsh BANK
-  Channel (fka Outfall)
-  Channel Pipe
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Access Pipe
-  Bleeder Pipe



1 inch = 175 feet

Prepared By: BC Stormwater Management Utility

Date Print: 11/21/13

File: C:\sethdata\projects\projectmaps\Benton Field Rd 2014-514