



# Beaufort County Public Works Stormwater Infrastructure Project Summary

**Project Summary:** Bridgewood Road Outfall

**Activity:** Routine/Preventive Maintenance

**Narrative Description of Project:**

Repaired workshelf.

**Completion:** Oct-13

2014-534 / Bridgewood Road Outfall	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
HAUL / Hauling	13.0	\$277.83	\$139.10	\$133.76	\$0.00	\$187.46	\$738.15
WSREP / Workshelf - Repair	21.0	\$487.95	\$87.00	\$44.15	\$0.00	\$223.08	\$842.18
<b>2014-534 / Bridgewood Road Outfall Sub Total</b>	<b>34.5</b>	<b>\$776.01</b>	<b>\$226.10</b>	<b>\$177.91</b>	<b>\$0.00</b>	<b>\$417.15</b>	<b>\$1,597.17</b>
<b>Grand Total</b>	<b>34.5</b>	<b>\$776.01</b>	<b>\$226.10</b>	<b>\$177.91</b>	<b>\$0.00</b>	<b>\$417.15</b>	<b>\$1,597.17</b>

Before



During



After




**Project:**  
**Bridgewood Road**  
**Outfall**

**Activity: Routine/**  
**Preventive**  
**Maintenance**

**Project #:**  
**2014-534**















**Township: St.**  
**Helena Island**

**Completed:**  
**September 2013**



**Legend**

**TYPE**

-  River
-  Creek/Stream
-  River/Creek/Marsh BANK
-  Channel (fka Outfall)
-  Channel Pipe
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Access Pipe
-  Bleeder Pipe



**1 inch = 118 feet**