



# Beaufort County Public Works

## Stormwater Infrastructure

### Project Summary

**Project Summary:** Oyster Street Outfall

**Activity:** Routine/Preventive Maintenance

**Narrative Description of Project:**

Project improved 350 L.F. of drainage system. Cleaned out 350 L.F. of channel.

**Completion:** Oct-13

2014-532 / Oyster Street	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
HAUL / Hauling	11.0	\$237.93	\$117.70	\$58.31	\$0.00	\$158.62	\$572.56
ODCO / Outfall ditch - cleaned out	25.0	\$571.36	\$102.72	\$53.17	\$0.00	\$384.60	\$1,111.84
ONJV / Onsite Job Visit	5.0	\$165.90	\$18.10	\$17.82	\$0.00	\$122.35	\$324.17
UTLOC / Utility locates	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
<b>2014-532 / Oyster Street Sub Total</b>	<b>42.0</b>	<b>\$995.65</b>	<b>\$238.52</b>	<b>\$129.30</b>	<b>\$0.00</b>	<b>\$678.80</b>	<b>\$2,042.26</b>
<b>Grand Total</b>	<b>42.0</b>	<b>\$995.65</b>	<b>\$238.52</b>	<b>\$129.30</b>	<b>\$0.00</b>	<b>\$678.80</b>	<b>\$2,042.26</b>

Before



During



After





**Project: Oyster Street**

**Activity: Routine/ Preventive Maintenance**

**Project #: 2014-532**

**Township: Bluffton**

**Completed: October 2013**

**Legend**

**TYPE**

- River
- Creek/Stream
- River/Creek/Marsh BANK
- Channel (fka Outfall)
- Channel Pipe
- Lateral
- Lateral Pipe
- Roadside
- Roadside Pipe
- Road Pipe
- Crossline Pipe
- Driveway Pipe
- Access Pipe
- Bleeder Pipe



1 inch = 110 feet