



Beaufort County Public Works Stormwater Infrastructure Project Summary

Project Summary: Polite Drive

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Project improved 315 L.F. of drainage system. Cleaned out 315 L.F. of roadside ditch. Constructed a flume for runoff. Repaired washout.

Completion: Sep-13

2014-520 / Polite Drive	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
HAUL / Hauling	20.5	\$443.35	\$219.35	\$171.66	\$0.00	\$295.61	\$1,129.97
ONJV / Onsite Job Visit	9.0	\$303.02	\$32.58	\$33.11	\$0.00	\$217.24	\$585.95
RPWO / Repaired Washout	16.0	\$338.71	\$31.11	\$45.10	\$0.00	\$173.40	\$588.32
RSDCL / Roadside Ditch - Cleanout	19.5	\$438.68	\$73.42	\$57.11	\$0.00	\$293.67	\$862.88
2014-520 / Polite Drive Sub Total	65.5	\$1,533.99	\$356.46	\$306.98	\$0.00	\$986.54	\$3,183.97
Grand Total	65.5	\$1,533.99	\$356.46	\$306.98	\$0.00	\$986.54	\$3,183.97

Before



During



After



Project: Polite Drive

**Activity: Routine/
Preventive
Maintenance**
















**Project #:
2014-520**

**Township: Port
Royal Island**

**Completed:
September 2013**

Legend

TYPE

-  River
-  Creek/Stream
-  River/Creek/Marsh BANK
-  Channel (fka Outfall)
-  Channel Pipe
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Access Pipe
-  Bleeder Pipe
-  Catch Basin

Cleaned out 315 LF
of roadside ditch.

Constructed a flume for
runoff. Repaired washout.



1 inch = 171 feet