



Beaufort County Public Works Stormwater Infrastructure Project Summary

Project Summary: Burton Wells Road Channel

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Project improved 2,645 L.F. of drainage system. Cleaned out 2,645 L.F. of channel.

Completion: Feb-14

2014-571 / Burton Wells Road Channel	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
HAUL / Hauling	8.0	\$173.04	\$85.60	\$29.70	\$0.00	\$115.36	\$403.70
ODCO / Outfall ditch - cleaned out	146.0	\$3,332.97	\$1,246.99	\$479.55	\$0.00	\$2,116.92	\$7,176.43
ONJV / Onsite Job Visit	20.5	\$645.12	\$74.21	\$39.59	\$0.00	\$436.12	\$1,195.04
2014-571 / Burton Wells Road Channel Sub Total	175.0	\$4,161.36	\$1,406.80	\$548.84	\$0.00	\$2,675.01	\$8,792.01
 Grand Total	 175.0	 \$4,161.36	 \$1,406.80	 \$548.84	 \$0.00	 \$2,675.01	 \$8,792.01

Before



During



After



Project: Burton Wells Road Channel

Activity: Routine/ Preventive Maintenance















Project #: 2014-571

Township: Port Royal Island

Completed: February 2014

Legend

TYPE

-  River
-  Creek/Stream
-  River/Creek/Marsh BANK
-  Channel (fka Outfall)
-  Channel Pipe
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Access Pipe
-  Bleeder Pipe



0 145 290 580 870 1,160
Feet

1 inch = 564 feet

Prepared By: BC Stormwater Management Utility

Date Print: 3/18/14

File: C:/sethdata/projects/projectmaps/Burton Wells Rd 2014-571