



Beaufort County Public Works Stormwater Infrastructure Project Summary

Project Summary: Providence Road Channel #1

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Completion: Mar-14

Project improved 890 L.F. of drainage system. Cleaned out 890 L.F. of channel.

2014-586 / Providence Road Channel #1	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.0	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
HAUL / Hauling	24.0	\$557.90	\$221.74	\$150.61	\$0.00	\$372.78	\$1,303.03
ODCO / Outfall ditch - cleaned out	40.0	\$879.51	\$153.87	\$49.65	\$0.00	\$441.60	\$1,524.63
ONJV / Onsite Job Visit	4.0	\$119.36	\$14.48	\$5.72	\$0.00	\$72.92	\$212.48
2014-586 / Providence Road Channel #1 Sub Total	68.0	\$1,556.77	\$390.09	\$205.98	\$0.00	\$887.30	\$3,040.13
Grand Total	68.0	\$1,556.77	\$390.09	\$205.98	\$0.00	\$887.30	\$3,040.13

Before



During



After



**Project: Providence
Road Channel #1**

**Activity: Routine/
Preventive
Maintenance**

**Project #:
2014-586**















**Township: Port
Royal Island**

**Completed:
March 2014**

Cleaned out 890
LF of channel.

Legend

TYPE

-  River
-  Creek/Stream
-  River/Creek/Marsh BANK
-  Channel (fka Outfall)
-  Channel Pipe
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Access Pipe
-  Bleeder Pipe



1 inch = 205 feet

Prepared By: BC Stormwater Management Utility

Date Print: 3/20/14

File:C:/sethdata/projects/projectmaps/Providence Rd Rd 2014-586