



Beaufort County
Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Scott Hill Road Channel #1

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Completion: Feb-14

Removed blockage from flapgate and 750 L.F. of channel. Repaired washout.

2014-579 / Scott Hill Road Channel #1	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
HAUL / Hauling	5.5	\$116.66	\$58.85	\$43.71	\$0.00	\$79.31	\$298.53
RB / Remove blockage from flowline	16.5	\$366.31	\$70.06	\$73.88	\$0.00	\$225.06	\$735.30
2014-579 / Scott Hill Road Channel #1 Sub Total	22.5	\$493.19	\$128.91	\$117.59	\$0.00	\$310.98	\$1,050.67
Grand Total	22.5	\$493.19	\$128.91	\$117.59	\$0.00	\$310.98	\$1,050.67

(Pictures Not Available)

Project: Scott Hill Road Channel #1

**Activity: Routine/
Preventive
Maintenance**

**Project #:
2014-579**

**Township: St.
Helena Island**

**Completed:
February 2014**

Legend

TYPE

- River
- Creek/Stream
- River/Creek/Marsh BANK
- Channel (fka Outfall)
- Channel Pipe
- Lateral
- Lateral Pipe
- Roadside
- Roadside Pipe
- Road Pipe
- Crossline Pipe
- Driveway Pipe
- Access Pipe
- Bleeder Pipe
- Flapgate

Removed blockage
from flapgate.

Repaired washout.

Removed blockages from
750 LF of channel.



1 inch = 167 feet