



Beaufort County Public Works Stormwater Infrastructure Project Summary

Project Summary: Folly Road Channel #1

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Completion: Feb-14

Project improved 1,056 L.F. of drainage system. Cleaned out 1,056 L.F. of channel.

2014-583 / Folly Road Channel #1	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
HAUL / Hauling	11.0	\$237.93	\$117.70	\$430.53	\$0.00	\$158.62	\$944.78
ODCO / Outfall ditch - cleaned out	54.0	\$1,189.21	\$370.74	\$68.23	\$0.00	\$794.16	\$2,422.33
ONJV / Onsite Job Visit	9.0	\$320.80	\$32.58	\$40.04	\$0.00	\$239.21	\$632.63
TC / Traffic Control - Jobsite	3.0	\$71.94	\$10.86	\$20.02	\$0.00	\$49.41	\$152.23
2014-583 / Folly Road Channel #1 Sub Total	77.5	\$1,830.11	\$531.88	\$558.82	\$0.00	\$1,248.02	\$4,168.82
Grand Total	77.5	\$1,830.11	\$531.88	\$558.82	\$0.00	\$1,248.02	\$4,168.82

Before



During



After



Project: Folly Road Channel #1

**Activity: Routine/
Preventive
Maintenance**

**Project #:
2014-583**

**Township: St.
Helena Island**

**Completed:
February 2014**

Legend

TYPE

- River
- Creek/Stream
- River/Creek/Marsh BANK
- Channel (fka Outfall)
- ▬ Channel Pipe
- Lateral
- ▬ Lateral Pipe
- Roadside
- ▬ Roadside Pipe
- ▬ Road Pipe
- ▬ Crossline Pipe
- ▬ Driveway Pipe
- ▬ Access Pipe
- Bleeder Pipe

Cleaned out 1,056
LF of channel.



1 inch = 147 feet

Prepared By: BC Stormwater Management Utility

Date Print: 3/20/14

File:C:/sethdata/projects/projectmaps/Folly Rd 2014-583