



# Beaufort County Public Works Stormwater Infrastructure Project Summary

**Project Summary:** Knightsbridge Road

**Activity:** Routine/Preventive Maintenance

**Narrative Description of Project:**

Repaired sinkhole.

**Completion:** Feb-14

2014-585 / Knightsbridge Road	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
HAUL / Hauling	10.0	\$216.30	\$107.00	\$169.23	\$0.00	\$144.20	\$636.73
ONJV / Onsite Job Visit	6.0	\$179.04	\$21.72	\$25.74	\$0.00	\$109.38	\$335.88
PRRECON / Project Reconnaissance	3.0	\$99.54	\$10.86	\$17.16	\$0.00	\$73.41	\$200.97
SR / Sinkhole repair	28.0	\$642.36	\$49.21	\$138.25	\$0.00	\$397.65	\$1,227.47
UTLOC / Utility locates	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
<b>2014-585 / Knightsbridge Road Sub Total</b>	<b>48.0</b>	<b>\$1,157.70</b>	<b>\$188.79</b>	<b>\$350.38</b>	<b>\$0.00</b>	<b>\$737.87</b>	<b>\$2,434.74</b>
<b>Grand Total</b>	<b>48.0</b>	<b>\$1,157.70</b>	<b>\$188.79</b>	<b>\$350.38</b>	<b>\$0.00</b>	<b>\$737.87</b>	<b>\$2,434.74</b>

Before



During



After



**Project:**  
**Knightsbridge  
Road**

**Activity: Routine/  
Preventive  
Maintenance**
















**Project #:**  
**2014-585**


**Township:**  
**Bluffton**

**Completed:**  
**February 2014**

**Legend**

**TYPE**

-  River
-  Creek/Stream
-  River/Creek/Marsh BANK
-  Channel (fka Outfall)
-  Channel Pipe
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Access Pipe
-  Bleeder Pipe
-  Catch Basin



**1 inch = 41 feet**

Prepared By: BC Stormwater Management Utility

Date Print: 3/18/14

File:C:/sethdata/projects/projectmaps/KnightsbridgeRd 2014-585