



Beaufort County Public Works Stormwater Infrastructure Project Summary

Project Summary: Major Road Channel #1,2 and 3

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Completion: Mar-14

Project improved 1,995 L.F. of drainage system. Cleaned out 1,995 L.F. of channel.

2014-584 / Major Road Channel #1,2 and 3	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
HAUL / Hauling	61.0	\$1,319.00	\$652.70	\$278.04	\$0.00	\$830.20	\$3,079.94
ODCO / Outfall ditch - cleaned out	93.0	\$2,014.40	\$843.59	\$320.01	\$0.00	\$1,271.75	\$4,449.75
ONJV / Onsite Job Visit	21.0	\$692.24	\$65.16	\$60.06	\$0.00	\$482.93	\$1,300.39
PP / Project Preparation	21.0	\$439.51	\$25.34	\$17.32	\$0.00	\$287.63	\$769.80
STBY / Stand By	7.0	\$151.41	\$74.90	\$19.86	\$0.00	\$85.47	\$331.64
2014-584 / Major Road Channel #1,2 and 3 Sub Total	203.5	\$4,626.79	\$1,661.69	\$695.29	\$0.00	\$2,964.59	\$9,948.36
Grand Total	203.5	\$4,626.79	\$1,661.69	\$695.29	\$0.00	\$2,964.59	\$9,948.36

Before




During



After





Project: Major Road Channel #1, #2, #3

Activity: Routine/ Preventive Maintenance

Project #: 2014-584

Township: St Helena Island

Completed: March 2014

Legend

- TYPE**
- River
 - Creek/Stream
 - River/Creek/Marsh BANK
 - Channel (fka Outfall)
 - Channel Pipe
 - Lateral
 - Lateral Pipe
 - Roadside
 - Roadside Pipe
 - Road Pipe
 - Crossline Pipe
 - Driveway Pipe
 - Access Pipe
 - Bleeder Pipe

Cleaned out 465 LF of roadside ditch.

Cleaned out 930 LF of channel.

Cleaned out 600 LF of channel.



1 inch = 232 feet