



Beaufort County Public Works Stormwater Infrastructure Project Summary

Project Summary: Mink Point Channel Pipe #1

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Removed blockages from flowline.

Completion: Feb-14

2014-575 / Mink Point Channel Pipe #1	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
FENINST / Fence Installation	13.5	\$282.56	\$16.29	\$6.62	\$0.00	\$179.55	\$485.02
HAUL / Hauling	10.0	\$216.30	\$107.00	\$16.55	\$0.00	\$144.20	\$484.05
LM / Loading Materials	10.0	\$216.30	\$72.76	\$27.14	\$0.00	\$132.30	\$448.50
ONJV / Onsite Job Visit	8.0	\$276.53	\$28.96	\$31.46	\$0.00	\$205.25	\$542.20
RB / Remove blockage from flowline	40.0	\$911.50	\$104.19	\$48.00	\$0.00	\$614.40	\$1,678.08
2014-575 / Mink Point Channel Pipe #1 Sub Total	82.0	\$1,913.42	\$329.20	\$129.77	\$0.00	\$1,282.31	\$3,654.70
Grand Total	82.0	\$1,913.42	\$329.20	\$129.77	\$0.00	\$1,282.31	\$3,654.70

Before



During



After



**Project: Mink Point
Blvd Channel Pipe
#1**

**Activity: Routine/
Preventive
Maintenance**

**Project #:
2014-575**

**Township: Port
Royal Island**

**Completed:
February 2014**

Legend

TYPE

- River
- Creek/Stream
- River/Creek/Marsh BANK
- Channel (fka Outfall)
- Channel Pipe
- Lateral
- Lateral Pipe
- Roadside
- Roadside Pipe
- Road Pipe
- Crossline Pipe
- Driveway Pipe
- Access Pipe
- Bleeder Pipe

Removed blockage
from flowline.



1 inch = 88 feet