



Beaufort County Public Works Stormwater Infrastructure Project Summary

Project Summary: Paige Point Bluff

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Replaced (1) driveway pipe.

Completion: Jul-14

2015-500 / Paige Point Bluff	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
DPRPL / Driveway Pipe - Replaced	24.0	\$575.46	\$60.07	\$204.68	\$0.00	\$349.80	\$1,190.01
HAUL / Hauling	6.0	\$129.78	\$64.20	\$69.47	\$0.00	\$86.52	\$349.97
2015-500 / Paige Point Bluff Sub Total	30.5	\$715.47	\$124.27	\$274.15	\$0.00	\$442.94	\$1,556.82
Grand Total	30.5	\$715.47	\$124.27	\$274.15	\$0.00	\$442.94	\$1,556.82

Before



During



After



Project: Paige Point Bluff

**Activity: Routine/
Preventive
Maintenance**















**Project #:
2015-500**

**Township:
Sheldon**

**Completed:
July 2014**

Legend

TYPE

-  River
-  Creek/Stream
-  River/Creek/Marsh BANK
-  Channel (fka Outfall)
-  Channel Pipe
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Access Pipe
-  Bleeder Pipe



1 inch = 117 feet