

Beaufort County Public Works Stormwater Infrastructure

Project Summary

Project Summary: Mint Farm Drive Channel #1

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Completion: Apr-14

Project improved 1,751 L.F. of drainage system. Cleaned out 1,751 L.F. of channel.

2014-600 / Mint Farm Drive Channel #1	Labor	Labor	Equipment	Material	Contractor	Indirect	
	Hours	Cost	Cost	Cost	Cost	Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
HAUL / Hauling	10.0	\$239.80	\$107.00	\$44.72	\$0.00	\$164.70	\$556.22
ODCO / Outfall ditch - cleaned out	50.0	\$1,037.10	\$152.61	\$41.28	\$0.00	\$555.20	\$1,786.19
ONJV / Onsite Job Visit	4.0	\$126.04	\$14.48	\$11.72	\$0.00	\$85.40	\$237.64
2014-600 / Mint Farm Drive Channel #1	65.0	\$1,423.40	\$274.09	\$97.72	\$0.00	\$818.53	\$2,613.74
Sub Total							
Grand Total	65.0	\$1,423.40	\$274.09	\$97.72	\$0.00	\$818.53	\$2,613.74

Before



After



