



Beaufort County
Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Mroz Road Wetlands Channel Crossing

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Project improved 3,495 L.F. of drainage system. Removed 3,495 L.F. of blockage from flowline by hand.

Completion: Feb-14

2014-567 / Mroz Road Wetlands Channel Crossing	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
ONJV / Onsite Job Visit	2.0	\$66.36	\$7.24	\$14.30	\$0.00	\$48.94	\$136.84
RB / Remove blockage from flowline	19.0	\$404.12	\$18.10	\$9.93	\$0.00	\$216.75	\$648.90
UTLOC / Utility locates	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
2014-567 / Mroz Road Wetlands Channel Crossing	22.0	\$490.94	\$25.34	\$24.23	\$0.00	\$278.92	\$819.43
Sub Total							
Grand Total	22.0	\$490.94	\$25.34	\$24.23	\$0.00	\$278.92	\$819.43

Before



During



After



**Project: Mroz Road
Wetlands Channel**

**Activity: Routine/
Preventive
Maintenance**
















**Project #:
2014-567**

**Township: Port
Royal Island**

**Completed:
February 2014**

Legend

TYPE

-  River
-  Creek/Stream
-  River/Creek/Marsh BANK
-  Channel (fka Outfall)
-  Channel Pipe
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Access Pipe
-  Bleeder Pipe
-  Catch Basin

Removed 3,495 LF of
blockage from flowline
by hand.



1 inch = 377 feet