



**Beaufort County  
Public Works  
Stormwater Infrastructure  
Project Summary**

**Project Summary:** Polowana Road Channel #1

**Activity:** Routine/Preventive Maintenance

**Narrative Description of Project:**

**Completion:** Mar-14

Project improved 420 L.F. of drainage system. Removed trash and blockages from flowline. Cleaned out 420 L.F. of channel.

2014-604 / Polowana Road Channel #1	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
HAUL / Hauling	7.5	\$162.23	\$80.25	\$580.09	\$0.00	\$108.15	\$930.72
ODCO / Outfall ditch - cleaned out	15.0	\$331.60	\$68.53	\$27.52	\$0.00	\$220.80	\$648.45
ONJV / Onsite Job Visit	3.0	\$132.81	\$10.86	\$8.79	\$0.00	\$101.88	\$254.34
<b>2014-604 / Polowana Road Channel #1 Sub Total</b>	<b>26.0</b>	<b>\$636.87</b>	<b>\$159.64</b>	<b>\$616.40</b>	<b>\$0.00</b>	<b>\$437.44</b>	<b>\$1,850.35</b>
<b>Grand Total</b>	<b>26.0</b>	<b>\$636.87</b>	<b>\$159.64</b>	<b>\$616.40</b>	<b>\$0.00</b>	<b>\$437.44</b>	<b>\$1,850.35</b>

Before



During



After



**Project: Polowana Road Channel #1**

**Activity: Routine/  
Preventive  
Maintenance**















**Project #:  
2014-604**

**Township: St.  
Helena Island**

**Completed:  
March 2014**

**Legend**

**TYPE**

-  River
-  Creek/Stream
-  River/Creek/Marsh BANK
-  Channel (fka Outfall)
-  Channel Pipe
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Access Pipe
-  Bleeder Pipe



1 inch = 167 feet