



# Beaufort County Public Works Stormwater Infrastructure Project Summary

**Project Summary:** Sun City Fire Station

**Activity:** Routine/Preventive Maintenance

**Narrative Description of Project:**

**Completion:** Apr-14

Reconstructed (1) catch basin lid to correct elevation. Installed sod for erosion control.

2014-610 / Sun City Fire Station	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
HAUL / Hauling	3.0	\$71.94	\$32.10	\$46.59	\$0.00	\$49.41	\$200.04
MHRA / Manhole Cover - Raised	33.0	\$713.87	\$69.14	\$131.66	\$0.00	\$435.33	\$1,350.00
ONJV / Onsite Job Visit	9.0	\$268.56	\$32.58	\$46.88	\$0.00	\$164.07	\$512.09
SI / Sod - Installation	16.0	\$327.27	\$14.48	\$20.64	\$0.00	\$208.28	\$570.67
<b>2014-610 / Sun City Fire Station Sub Total</b>	<b>61.5</b>	<b>\$1,391.87</b>	<b>\$148.30</b>	<b>\$245.77</b>	<b>\$0.00</b>	<b>\$863.71</b>	<b>\$2,649.65</b>
<b>Grand Total</b>	<b>61.5</b>	<b>\$1,391.87</b>	<b>\$148.30</b>	<b>\$245.77</b>	<b>\$0.00</b>	<b>\$863.71</b>	<b>\$2,649.65</b>

Before



During



After



**Project: Sun City Fire Station**

**Activity: Routine/ Preventive Maintenance**
















**Project #: 2014-610**

**Township: Bluffton**


**Completed: April 2014**

**Legend**

**TYPE**

-  River
-  Creek/Stream
-  River/Creek/Marsh BANK
-  Channel (fka Outfall)
-  Channel Pipe
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Access Pipe
-  Bleeder Pipe
-  Catch Basin

Reconstructed (1) catch basin lid to correct elevation. Installed sod for erosion control.



1 inch = 39 feet