



**Beaufort County
Public Works
Stormwater Infrastructure
Project Summary**

Project Summary: Washington Farm Road Channel #1

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Project improved 400 L.F. of drainage system. Removed blockage from flowline due to beaver dam. Cleaned out 400 L.F. of creek.

Completion: Apr-14

2014-581 / Washington Farm Road Channel #1	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
HAUL / Hauling	6.0	\$132.13	\$64.20	\$51.89	\$0.00	\$88.57	\$336.79
ODCO / Outfall ditch - cleaned out	15.0	\$331.60	\$137.38	\$34.40	\$0.00	\$220.80	\$724.18
ONJV / Onsite Job Visit	13.0	\$387.92	\$47.06	\$28.13	\$0.00	\$236.99	\$700.10
WSREP / Workshelf - Repair	9.0	\$184.10	\$30.66	\$36.18	\$0.00	\$116.01	\$366.95
2014-581 / Washington Farm Road Channel #1	54.0	\$1,278.10	\$311.85	\$178.12	\$0.00	\$823.54	\$2,591.62
Sub Total							
Grand Total	54.0	\$1,278.10	\$311.85	\$178.12	\$0.00	\$823.54	\$2,591.62

Before



During



After



Project: Washington Farm Road Channel #1

Activity: Routine/ Preventive Maintenance

Project #: 2014-581

Township: Sheldon

Completed: April 2014



Removed blockage from flowline due to beaver dam.

Cleaned out 400 LF of creek.

KINLOCH RD

WASHINGTON FARM RD

Legend

TYPE

- River
- Creek/Stream
- River/Creek/Marsh BANK
- Channel (fka Outfall)
- Channel Pipe
- Lateral
- Lateral Pipe
- Roadside
- Roadside Pipe
- Road Pipe
- Crossline Pipe
- Driveway Pipe
- Access Pipe
- Bleeder Pipe
- Catch Basin



1 inch = 235 feet