



Beaufort County
Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Parker Drive Channel #1

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Completion: Jan-14

Project improved 1,400 L.F. of drainage system. Cleaned out 1,400 L.F. channel.

2014-566 / Parker Drive Channel #1	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
HAUL / Hauling	6.0	\$127.26	\$64.20	\$23.24	\$0.00	\$86.52	\$301.22
ODCO / Outfall ditch - cleaned out	12.0	\$269.64	\$174.51	\$33.20	\$0.00	\$180.72	\$658.07
2014-566 / Parker Drive Channel #1 Sub Total	18.5	\$407.13	\$238.71	\$56.44	\$0.00	\$273.86	\$976.14
Grand Total	18.5	\$407.13	\$238.71	\$56.44	\$0.00	\$273.86	\$976.14

(Pictures Not Available)

Project: Parker Drive Channel #1

**Activity: Routine/
Preventive
Maintenance**
















**Project #:
2014-566**

**Township: Port
Royal Island**

**Completed:
January 2014**

Legend

TYPE

-  River
-  Creek/Stream
-  River/Creek/Marsh BANK
-  Channel (fka Outfall)
-  Channel Pipe
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Access Pipe
-  Bleeder Pipe
-  Catch Basin



1 inch = 270 feet