



Beaufort County
Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Prescott Road Channel #1

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Project improved 310 L.F. of drainage system. Cleaned out 310 L.F. of channel.

Completion: Jan-14

2014-562 / Prescott Road Channel #1	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
HAUL / Hauling	11.0	\$235.41	\$117.70	\$66.00	\$0.00	\$158.62	\$577.73
ODCO / Outfall ditch - cleaned out	30.0	\$654.00	\$119.35	\$30.05	\$0.00	\$433.50	\$1,236.90
ONJV / Onsite Job Visit	4.0	\$119.36	\$14.48	\$5.78	\$0.00	\$72.92	\$212.54
2014-562 / Prescott Road Channel #1 Sub Total	45.5	\$1,019.00	\$251.53	\$101.83	\$0.00	\$671.66	\$2,044.02
Grand Total	45.5	\$1,019.00	\$251.53	\$101.83	\$0.00	\$671.66	\$2,044.02

Before



During



After



Project: Prescott Road

**Activity: Routine/
Preventive
Maintenance**















**Project #:
2014-562**

**Township:
Sheldon**

**Completed:
January 2014**

Legend

TYPE

-  River
-  Creek/Stream
-  River/Creek/Marsh BANK
-  Channel (fka Outfall)
-  Channel Pipe
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Access Pipe
-  Bleeder Pipe

Cleaned out 310
LF of channel.

PRESCOTT RD

SOLOMON WHITE LN



1 inch = 173 feet