



Beaufort County
Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Capehart Circle Subdivision

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Completion: Jul-14

Project improved 890 L.F. of drainage system. Removed 100 L.F. of blockage from roadside ditch by hand. Cleaned out 550 L.F. of roadside ditch and 240 L.F. of channel.

2015-505 / Capehart Circle Subdivision	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
HAUL / Hauling	12.0	\$259.56	\$128.40	\$42.51	\$0.00	\$150.94	\$581.41
ODCO / Outfall ditch - cleaned out	36.0	\$868.09	\$235.00	\$52.32	\$0.00	\$596.39	\$1,751.80
ONJV / Onsite Job Visit	3.0	\$132.81	\$10.86	\$6.40	\$0.00	\$101.88	\$251.95
RB / Remove blockage from flowline	6.0	\$137.36	\$7.24	\$9.60	\$0.00	\$84.66	\$238.86
2015-505 / Capehart Circle Subdivision	57.5	\$1,408.05	\$381.50	\$110.83	\$0.00	\$940.49	\$2,840.87
Sub Total							
Grand Total	57.5	\$1,408.05	\$381.50	\$110.83	\$0.00	\$940.49	\$2,840.87

Before



After




Project: Capehart Circle

**Activity: Routine/
Preventive
Maintenance**

**Project #:
2015-505**















**Township: Port
Royal Island**

**Completed:
July 2014**



Legend

TYPE

-  River
-  Creek/Stream
-  River/Creek/Marsh BANK
-  Channel (fka Outfall)
-  Channel Pipe
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Access Pipe
-  Bleeder Pipe



1 inch = 96 feet