

## Beaufort County Public Works Stormwater Infrastructure

## - . . . .

Project Summary

Project Summary: Paige Point Bluff

Activity: Routine/Preventive Maintenance

**Narrative Description of Project:** 

Completion: Aug-14

Project improved 560 L.F. of drainage system. Cleaned out 560 L.F. of channel. Jetted (1) crossline pipe.

2015-525 / Paige Point Bluff	Labor	Labor	Equipment	Material	Contractor	Indirect	
	Hours	Cost	Cost	Cost	Cost	Labor	<b>Total Cost</b>
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
CLPJT / Crossline Pipe - Jetted	4.0	\$89.36	\$44.32	\$43.00	\$0.00	\$59.82	\$236.50
HAUL / Hauling	15.0	\$324.45	\$160.50	\$84.53	\$0.00	\$216.30	\$785.78
ODCO / Channel - cleaned out	20.0	\$456.10	\$102.72	\$43.56	\$0.00	\$307.20	\$909.58
ONJV / Onsite Job Visit	2.0	\$88.54	\$7.24	\$6.06	\$0.00	\$67.92	\$169.76
2015-525 / Paige Point Bluff	41.5	\$968.68	\$314.78	\$177.15	\$0.00	\$657.86	\$2,118.47
Sub Total							
Grand Total	41.5	\$968.68	\$314.78	\$177.15	\$0.00	\$657.86	\$2,118.47









