



# Beaufort County Public Works Stormwater Infrastructure Project Summary

**Project Summary:** Pleasant Point Drive Channel

**Activity:** Routine/Preventive Maintenance

**Narrative Description of Project:**

**Completion:** June-14

Project improved 1,719 L.F. of drainage system. Bush hogged 1,719 L.F. of workshelf. Cleaned out 473 L.F. of channel.

2014-634 / Pleasant Point Drive Channel	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
HAUL / Hauling	13.5	\$292.01	\$144.45	\$104.64	\$0.00	\$194.67	\$735.77
ODCO / Outfall ditch - cleaned out	24.0	\$575.52	\$128.74	\$37.21	\$0.00	\$370.96	\$1,112.43
ONJV / Onsite Job Visit	6.0	\$179.04	\$21.72	\$12.76	\$0.00	\$109.38	\$322.90
WSBH / Workshelf - Bush Hogged	38.0	\$873.75	\$192.25	\$97.04	\$0.00	\$569.18	\$1,732.22
<b>2014-634 / Pleasant Point Drive Channel</b>	<b>82.0</b>	<b>\$1,930.55</b>	<b>\$487.16</b>	<b>\$251.64</b>	<b>\$0.00</b>	<b>\$1,250.81</b>	<b>\$3,920.16</b>
<b>Sub Total</b>							
<b>Grand Total</b>	<b>82.0</b>	<b>\$1,930.55</b>	<b>\$487.16</b>	<b>\$251.64</b>	<b>\$0.00</b>	<b>\$1,250.81</b>	<b>\$3,920.16</b>

Before



During



**Project: Pleasant Point Drive**

**Activity: Routine/ Preventive Maintenance**

**Project #: 2014-634**

**Township: Lady's Island**

**Completed: June 2014**



1 inch = 208 feet