



Beaufort County Public Works Stormwater Infrastructure Project Summary

Project Summary: Airport Circle

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Completion: June-14

Project improved 467 L.F. of drainage system. Bush hogged 467 L.F. of channel. Cleaned out 220 L.F. of channel.

2014-633 / Airport Circle	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
DLO / Ditch Layout	6.0	\$143.88	\$7.24	\$10.13	\$0.00	\$92.74	\$253.99
HAUL / Hauling	11.5	\$248.75	\$123.05	\$52.32	\$0.00	\$165.83	\$589.95
ODBH / Outfall ditch - bushhogged	6.0	\$134.10	\$40.10	\$22.49	\$0.00	\$86.67	\$283.36
ODCO / Outfall ditch - cleaned out	30.0	\$719.40	\$152.61	\$55.09	\$0.00	\$463.70	\$1,390.80
ONJV / Onsite Job Visit	3.0	\$89.52	\$10.86	\$15.95	\$0.00	\$54.69	\$171.02
PRRECON / Project Reconnaissance	2.0	\$88.54	\$7.24	\$6.38	\$0.00	\$67.92	\$170.08
2014-633 / Airport Circle	59.0	\$1,434.42	\$341.10	\$162.36	\$0.00	\$938.17	\$2,876.04
Sub Total							
Grand Total	59.0	\$1,434.42	\$341.10	\$162.36	\$0.00	\$938.17	\$2,876.04

Before



During



After



Project: Airport Circle

**Activity: Routine/
Preventive
Maintenance**















**Project #:
2014-663**

**Township: Lady's
Island**

**Completed:
June 2014**

Legend

TYPE

-  River
-  Creek/Stream
-  River/Creek/Marsh BANK
-  Channel (fka Outfall)
-  Channel Pipe
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Access Pipe
-  Bleeder Pipe



Bush hogged 327
LF of channel.

Cleaned out and bush
hogged 140 LF of channel.

Cleaned out 80
LF of channel.

AIRPORT CIR

D/W



1 inch = 109 feet