



**Beaufort County**  
**Public Works**  
**Stormwater Infrastructure**  
*Project Summary*

**Project Summary:** St. Helena Island Tree Removal - James D. Washington Road

**Activity:** Routine/Preventive Maintenance

**Narrative Description of Project:**  
Removed fallen tree from workshelf.

**Completion:** Apr-15

<b>2015-607 / St. Helena Island Tree Removal</b>	<b>Labor Hours</b>	<b>Labor Cost</b>	<b>Equipment Cost</b>	<b>Material Cost</b>	<b>Contractor Cost</b>	<b>Indirect Labor</b>	<b>Total Cost</b>
AUDIT / Audit Project	0.5	\$11.40	\$0.00	\$0.00	\$0.00	\$6.62	\$18.01
ONJV / Onsite Job Visit	3.0	\$99.54	\$10.86	\$9.65	\$0.00	\$73.41	\$193.46
RMTRW / Remove trees - Workshelf	20.0	\$432.65	\$17.70	\$10.42	\$0.00	\$285.90	\$746.67
<b>2015-607 / St. Helena Island Tree Removal Sub Total</b>	<b>23.5</b>	<b>\$543.59</b>	<b>\$28.56</b>	<b>\$20.07</b>	<b>\$0.00</b>	<b>\$365.92</b>	<b>\$958.14</b>
<b>Grand Total</b>	<b>23.5</b>	<b>\$543.59</b>	<b>\$28.56</b>	<b>\$20.07</b>	<b>\$0.00</b>	<b>\$365.92</b>	<b>\$958.14</b>

During



After





Project: SHI Tree Removal-James D Washington Road

Activity: Routine/ Preventive Maintenance

Project #: 2015-607A

Township: St.Helena Island

Completed: April 2015

**Legend**

**Drainage Type**

- Access Pipe
- Bleeder Pipe
- Channel Pipe
- Channel
- Stream
- Crossline Pipe
- Driveway Pipe
- Lateral
- Lateral Pipe
- River
- Road Pipe
- Roadside
- Roadside Pipe

0 40 80 160 240 320 Feet

1 inch = 170 feet