



Beaufort County
Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Burton Wells Road Channel #1

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Project improved 2,925 L.F. of drainage system. Reconstructed 1,600 L.F. of workshelf. Cleaned out 1,325 L.F. of channel. Installed (3) bleeder pipes.

Completion: Jun-15

2015-609 / Burton Wells Channel #1	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$11.40	\$0.00	\$0.00	\$0.00	\$6.62	\$18.01
BPINST / Bleeder pipe - Installed	30.0	\$672.40	\$85.29	\$229.52	\$0.00	\$451.40	\$1,438.61
CCO / Channel - cleaned out	61.0	\$1,284.38	\$264.29	\$108.48	\$0.00	\$862.82	\$2,519.97
HAUL / Hauling	82.0	\$1,773.66	\$655.18	\$646.48	\$0.00	\$1,194.74	\$4,270.06
ONJV / Onsite Job Visit	41.0	\$1,326.18	\$145.30	\$88.53	\$0.00	\$949.82	\$2,509.83
WSREC / Workshelf - Reconstructed	190.0	\$4,121.90	\$713.04	\$634.83	\$0.00	\$2,726.70	\$8,196.47
2015-609 / Burton Wells Channel #1 Sub Total	404.5	\$9,189.92	\$1,863.10	\$1,707.85	\$0.00	\$6,192.09	\$18,952.96
Grand Total	404.5	\$9,189.92	\$1,863.10	\$1,707.85	\$0.00	\$6,192.09	\$18,952.96

Before



During



After




Project: Burton Wells Road Channel #1

Activity: Routine/ Preventive Maintenance

Project #: 2015-609














Township: Port Royal Island

Completed: June 2015



Legend

Drainage Type

-  Access Pipe
-  Bleeder Pipe
-  Channel Pipe
-  Channel
-  Stream
-  Crossline Pipe
-  Driveway Pipe
-  Lateral
-  Lateral Pipe
-  River
-  Road Pipe
-  Roadside
-  Roadside Pipe



1 inch = 500 feet

Prepared By: BC Stormwater Management Utility

Date Print: 08/05/2015

File: C:\project summaries map\Burton Wells Road Channel #1_2015-609