



**Beaufort County**  
**Public Works**  
**Stormwater Infrastructure**  
*Project Summary*

**Project Summary:** Capehart Circle Channel #2

**Activity:** Routine/Preventive Maintenance

**Narrative Description of Project:**

Project improved 460 L.F. of drainage system. Cleaned out 400 L.F. of channel. Jetted (1) access pipe, (1) crossline pipe and 60 L.F. of channel pipe.

**Completion:** Jul-15

<b>2016-518 / Capehart Circle Ch #2</b>	<b>Labor Hours</b>	<b>Labor Cost</b>	<b>Equipment Cost</b>	<b>Material Cost</b>	<b>Contractor Cost</b>	<b>Indirect Labor</b>	<b>Total Cost</b>
AUDIT / Audit Project	0.5	\$11.75	\$0.00	\$0.00	\$0.00	\$6.62	\$18.36
CCO / Channel - cleaned out	40.0	\$911.82	\$160.54	\$21.84	\$0.00	\$590.10	\$1,684.29
CLPJT / Crossline Pipe - Jetted	6.0	\$133.70	\$26.04	\$20.60	\$0.00	\$86.04	\$266.38
HAUL / Hauling	10.0	\$222.80	\$79.90	\$42.40	\$0.00	\$144.20	\$489.30
<b>2016-518 / Capehart Circle Ch #2 Sub Total</b>	<b>56.5</b>	<b>\$1,280.06</b>	<b>\$266.48</b>	<b>\$84.84</b>	<b>\$0.00</b>	<b>\$826.95</b>	<b>\$2,458.33</b>
<b>Grand Total</b>	<b>56.5</b>	<b>\$1,280.06</b>	<b>\$266.48</b>	<b>\$84.84</b>	<b>\$0.00</b>	<b>\$826.95</b>	<b>\$2,458.33</b>

Before




During



After







Project: Capehart Circle Channel #2

Activity: Routine/ Preventive Maintenance

Project #: 2016-518

Township: Port Royal Island

Completed: July 2015

**Legend**

**Drainage Type**

- Access Pipe
- Bleeder Pipe
- Channel Pipe
- Channel
- Stream
- Crossline Pipe
- Driveway Pipe
- Lateral
- Lateral Pipe
- River
- Road Pipe
- Roadside
- Roadside Pipe

0 50 100 200 300 400 Feet

1 inch = 210 feet

Prepared By: BC Stormwater Management Utility  
Date Print:07/20/15

File:C:\project summaries map\Capehart Circle Channel #2\_2016-518