



Beaufort County
Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Powell Drive

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Project improved 579 L.F. of drainage system. Removed fallen tree from workshelf. Cleaned out 579 L.F. of channel.

Completion: Jan-15

2015-566 / Powell Drive	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
HAUL / Hauling	2.0	\$43.26	\$21.40	\$5.26	\$0.00	\$28.84	\$98.76
RB / Remove blockage from flowline	20.0	\$457.40	\$71.74	\$28.93	\$0.00	\$308.25	\$866.32
2015-566 / Powell Drive	22.5	\$510.89	\$93.14	\$34.19	\$0.00	\$343.70	\$981.92
Sub Total							
Grand Total	22.5	\$510.89	\$93.14	\$34.19	\$0.00	\$343.70	\$981.92

Before



During



After



Project: Powell Drive

**Activity: Routine/
Preventive
Maintenance**















**Project #:
2015-566**

**Township: Port
Royal Island**

**Completed:
January 2015**

Legend

TYPE

-  River
-  Creek/Stream
-  River/Creek/Marsh BANK
-  Channel (fka Outfall)
-  Channel Pipe
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Access Pipe
-  Bleeder Pipe

Removed fallen
tree from workshelf.

Cleaned out 579
LF of channel.

0 30 60 120 180 240
Feet

1 inch = 122 feet

Prepared By: BC Stormwater Management Utility

Date Print: 1/16/15

File: C:/sethdata/projects/projectmaps/Powell Dr 2015-566