



# Beaufort County Public Works Stormwater Infrastructure Project Summary

**Project Summary:** Robert Smalls Parkway Channel #1

**Activity:** Routine/Preventive Maintenance


**Narrative Description of Project:**

Project improved 250 L.F. of drainage system. Removed blockages from flowline. Cleaned out 250 L.F. of channel.

**Completion:** Nov-14

<b>2015-557 / Robert Smalls Pkwy Ch #1</b>	<b>Labor Hours</b>	<b>Labor Cost</b>	<b>Equipment Cost</b>	<b>Material Cost</b>	<b>Contractor Cost</b>	<b>Indirect Labor</b>	<b>Total Cost</b>
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
HAUL / Hauling	17.0	\$372.41	\$181.90	\$62.70	\$0.00	\$249.24	\$866.25
ODCO / Channel - cleaned out	60.0	\$1,372.22	\$292.86	\$37.96	\$0.00	\$924.75	\$2,627.79
ONJV / Onsite Job Visit	8.0	\$252.08	\$28.96	\$19.68	\$0.00	\$170.80	\$471.52
<b>2015-557 / Robert Smalls Parkway Ch #1 Sub Total</b>	<b>85.5</b>	<b>\$2,006.94</b>	<b>\$503.72</b>	<b>\$120.34</b>	<b>\$0.00</b>	<b>\$1,351.40</b>	<b>\$3,982.41</b>
<b>Grand Total</b>	<b>85.5</b>	<b>\$2,006.94</b>	<b>\$503.72</b>	<b>\$120.34</b>	<b>\$0.00</b>	<b>\$1,351.40</b>	<b>\$3,982.41</b>

Before



During



After




**Project: Robert Smalls Pkwy Channel # 1**

**Activity: Routine/ Preventive Maintenance**

**Project #: 2015-557**

**Township: Port Royal Island**

**Completed: November 2014**



**Legend**

TYPE	
	River
	Creek/Stream
	River/Creek/Marsh BANK
	Channel (fka Outfall)
	Channel Pipe
	Lateral
	Lateral Pipe
	Roadside
	Roadside Pipe
	Road Pipe
	Crossline Pipe
	Driveway Pipe
	Access Pipe
	Bleeder Pipe



1 inch = 288 feet