



**Beaufort County
Public Works
Stormwater Infrastructure
Project Summary**

Project Summary: Burton Wells Road

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Removed blockages from flowline.

Completion: Jan-15

2015-529 / Burton Wells Road	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
HAUL / Hauling	3.0	\$64.89	\$32.10	\$5.70	\$0.00	\$43.26	\$145.95
RB / Remove blockage from flowline	12.0	\$274.44	\$27.49	\$19.95	\$0.00	\$184.95	\$506.83
2015-529 / Burton Wells Road Sub Total	15.5	\$349.56	\$59.59	\$25.65	\$0.00	\$234.83	\$669.63
Grand Total	15.5	\$349.56	\$59.59	\$25.65	\$0.00	\$234.83	\$669.63

Before



During



After





Project: Burton Wells Road

Activity: Routine/ Preventive Maintenance















Project #: 2015-529

Township: Port Royal Island

Completed: January 2015

Legend

TYPE

-  River
-  Creek/Stream
-  River/Creek/Marsh BANK
-  Channel (fka Outfall)
-  Channel Pipe
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Access Pipe
-  Bleeder Pipe



1 inch = 200 feet