



# Beaufort County Public Works Stormwater Infrastructure Project Summary

**Project Summary:** Jennings Road

**Activity:** Routine/Preventive Maintenance

**Narrative Description of Project:**

Project improved 920 L.F. of drainage system. Cleaned out 920 L.F. of roadside ditch. Jetted (1) crossline pipe and (1) driveway pipe. Hydroseeded for erosion control.

**Completion:** Dec-14

| 2015-536 / Jennings Road          | Labor Hours  | Labor Cost        | Equipment Cost  | Material Cost   | Contractor Cost | Indirect Labor    | Total Cost        |
|-----------------------------------|--------------|-------------------|-----------------|-----------------|-----------------|-------------------|-------------------|
| AUDIT / Audit Project             | 0.5          | \$10.23           | \$0.00          | \$0.00          | \$0.00          | \$6.62            | \$16.85           |
| DPJT / Driveway Pipe - Jetted     | 10.0         | \$223.38          | \$110.80        | \$33.15         | \$0.00          | \$149.55          | \$516.88          |
| HAUL / Hauling                    | 30.0         | \$648.90          | \$321.00        | \$94.73         | \$0.00          | \$432.60          | \$1,497.23        |
| ODCO / Channel - cleaned out      | 64.0         | \$1,434.78        | \$281.50        | \$131.66        | \$0.00          | \$960.21          | \$2,808.15        |
| ONJV / Onsite Job Visit           | 18.0         | \$577.20          | \$65.16         | \$32.70         | \$0.00          | \$403.02          | \$1,078.08        |
| RSDCL / Roadside Ditch - Cleanout | 35.0         | \$783.58          | \$195.98        | \$48.62         | \$0.00          | \$524.16          | \$1,552.34        |
| <b>2015-536 / Jennings Road</b>   | <b>157.5</b> | <b>\$3,678.07</b> | <b>\$974.44</b> | <b>\$340.86</b> | <b>\$0.00</b>   | <b>\$2,476.15</b> | <b>\$7,469.53</b> |
| <b>Sub Total</b>                  |              |                   |                 |                 |                 |                   |                   |
| <b>Grand Total</b>                | <b>157.5</b> | <b>\$3,678.07</b> | <b>\$974.44</b> | <b>\$340.86</b> | <b>\$0.00</b>   | <b>\$2,476.15</b> | <b>\$7,469.53</b> |

Before



During



After



**Project: Jennings Road Map 1**

**Activity: Routine/ Preventive Maintenance**

**Project #: 2015-536**

**Township: Port Royal Island**

**Completed: December 2014**



**Legend**

**TYPE**

- River
- Creek/Stream
- River/Creek/Marsh BANK
- Channel (fka Outfall)
- Channel Pipe
- Lateral
- Lateral Pipe
- Roadside
- Roadside Pipe
- Road Pipe
- Crossline Pipe
- Driveway Pipe
- Access Pipe
- Bleeder Pipe



**1 inch = 167 feet**


**Project: Jennings  
Road Map 2**

**Activity: Vacuum  
Truck**

**Project #:  
2015-536**

**Township: Port  
Royal Island**

**Completed:  
December 2014**



**Legend**

**TYPE**

- River
- Creek/Stream
- River/Creek/Marsh BANK
- Channel (fka Outfall)
- Channel Pipe
- Lateral
- Lateral Pipe
- Roadside
- Roadside Pipe
- Road Pipe
- Crossline Pipe
- Driveway Pipe
- Access Pipe
- Bleeder Pipe



1 inch = 72 feet