



Beaufort County Public Works Stormwater Infrastructure Project Summary

Project Summary: Pleasant Point Drive

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Project improved 472 L.F. of drainage system. Reset (4) catch basin lids. Cleaned out 472 L.F. of channel.

Completion: Nov-14

2015-542 / Pleasant Point Drive	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
CBREP / Catch basin - repaired	6.0	\$119.22	\$32.86	\$12.20	\$0.00	\$76.32	\$240.60
HAUL / Hauling	5.5	\$124.84	\$58.85	\$48.80	\$0.00	\$84.44	\$316.93
LM / Loading Materials	8.0	\$158.96	\$36.48	\$27.45	\$0.00	\$101.76	\$324.65
ODCO / Channel - cleaned out	45.0	\$1,030.18	\$137.45	\$73.23	\$0.00	\$650.25	\$1,891.10
ONJV / Onsite Job Visit	20.0	\$514.70	\$143.20	\$39.53	\$0.00	\$326.50	\$1,023.93
2015-542 / Pleasant Point Drive Sub Total	85.0	\$1,958.13	\$408.84	\$201.21	\$0.00	\$1,245.88	\$3,814.05
Grand Total	85.0	\$1,958.13	\$408.84	\$201.21	\$0.00	\$1,245.88	\$3,814.05

Before



During



After



Project: Pleasant Point Drive Channel #1

Activity: Routine/ Preventive Maintenance
















Project #: 2015-542


Township: Lady's Island

Completed: November 2014

Legend

TYPE

-  River
-  Creek/Stream
-  River/Creek/Marsh BANK
-  Channel (fka Outfall)
-  Channel Pipe
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Access Pipe
-  Bleeder Pipe
-  Catch Basin



1 inch = 178 feet