

Beaufort County Public Works Stormwater Infrastructure

Project Summary

Project Summary: Bluffton Valley Drains

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Completion: Aug-14


Project improved 16,008 L.F. of drainage system. Cleaned 16,008 L.F. of valley drains. This project consisted of the following areas: Buck Point Road (3,250 L.F.), Ballfield Road (2,730 L.F.), Lake View Court (7,000 L.F.) and Mammy Grant Road (3,028 L.F.)


2015-315 / Bluffton Valley Drains	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
COVD / Cleaned Out Valley Drains	40.0	\$841.81	\$160.40	\$150.19	\$0.00	\$553.00	\$1,705.40
HAUL / Hauling	17.0	\$367.71	\$181.90	\$108.24	\$0.00	\$211.99	\$869.84
ONJV / Onsite Job Visit	2.0	\$66.36	\$7.24	\$9.09	\$0.00	\$48.94	\$131.63
2015-315 / Bluffton Valley Drains Sub Total	59.5	\$1,286.11	\$349.54	\$267.52	\$0.00	\$820.55	\$2,723.71
Grand Total	59.5	\$1,286.11	\$349.54	\$267.52	\$0.00	\$820.55	\$2,723.71

















File:C:/sethdata/projects/projectmaps/Mammy Grant Rd 2015-315