



**Beaufort County**  
**Public Works**  
**Stormwater Infrastructure**  
*Project Summary*

**Project Summary:** Wimbee Creek Road Channel #2

**Activity:** Routine/Preventive Maintenance

**Narrative Description of Project:**

Project improved 40 L.F. of drainage system. Cleaned out 40 L.F. of roadside ditch.

**Completion:** Nov-14

<b>2015-556 / Wimbee Creek Road Ch #2</b>	<b>Labor Hours</b>	<b>Labor Cost</b>	<b>Equipment Cost</b>	<b>Material Cost</b>	<b>Contractor Cost</b>	<b>Indirect Labor</b>	<b>Total Cost</b>
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
HAUL / Hauling	8.0	\$184.79	\$85.60	\$22.80	\$0.00	\$125.61	\$418.80
RSDCL / Roadside Ditch - Cleanout	9.0	\$202.50	\$50.62	\$19.95	\$0.00	\$135.54	\$408.61
<b>2015-556 / Wimbee Creek Road Ch #2 Sub Total</b>	<b>17.5</b>	<b>\$397.52</b>	<b>\$136.22</b>	<b>\$42.75</b>	<b>\$0.00</b>	<b>\$267.77</b>	<b>\$844.26</b>
 <b>Grand Total</b>	 <b>17.5</b>	 <b>\$397.52</b>	 <b>\$136.22</b>	 <b>\$42.75</b>	 <b>\$0.00</b>	 <b>\$267.77</b>	 <b>\$844.26</b>

Before



During



After





**Project: Wimbee  
Creek Road  
Channel 2**

**Activity: Routine/  
Preventive  
Maintenance**















**Project #:  
2015-556**

**Township:  
Sheldon**

**Completed:  
November 2014**

**Legend**

**TYPE**

-  River
-  Creek/Stream
-  River/Creek/Marsh BANK
-  Channel (fka Outfall)
-  Channel Pipe
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Access Pipe
-  Bleeder Pipe



0 30 60 120 180 240  
Feet

1 inch = 121 feet

Prepared By: BC Stormwater Management Utility

Date Print: 2/3/15

File: C:/sethdata/projects/projectmaps/Wimbee Creek Rd 2015-556