



Beaufort County Public Works Stormwater Infrastructure Project Summary

Project Summary: Middlefield Circle

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Project improved 3,490 L.F. of drainage system. Cleaned out 3,490 L.F. of channel.

Completion: Feb-15

2015-573 / Middlefield Circle	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.23	\$0.00	\$0.00	\$0.00	\$6.62	\$16.85
CCO / Channel - cleaned out	40.0	\$879.50	\$239.92	\$27.95	\$0.00	\$463.70	\$1,611.07
ONJV / Onsite Job Visit	2.0	\$88.54	\$7.24	\$3.56	\$0.00	\$67.92	\$167.26
PRRECON / Project Reconnaissance	2.0	\$59.68	\$7.24	\$1.78	\$0.00	\$36.46	\$105.16
RB / Remove blockage from flowline	20.0	\$439.75	\$119.96	\$30.10	\$0.00	\$231.85	\$821.66
2015-573 / Middlefield Circle Sub Total	64.5	\$1,477.70	\$374.36	\$63.39	\$0.00	\$806.54	\$2,721.99
Grand Total	64.5	\$1,477.70	\$374.36	\$63.39	\$0.00	\$806.54	\$2,721.99

Before



During



After




Project: Middlefield Circle

Activity: Routine/
Preventive
Maintenance

Project #:
2015-573

Township:
Sheldon

Completed:
February 2015



Legend

Drainage Type

- River
- Stream
- Channel
- Lateral
- Lateral Pipe
- Roadside
- Roadside Pipe
- Road Pipe
- Crossline
- D/W
- Access
- Piped
- Bleeder



1 inch = 500 feet