



Beaufort County Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Candy Johnson Drive Channel #1

Activity: Routine/Preventive Maintenance

Duration: 02/07/2018

Narrative Description of Project:

Project improved 646 L.F. of drainage system. Cleaned out 646 L.F. of channel.

2018-571 / Candy Johnson Drive Channel #1

	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.90	\$0.00	\$0.00	\$0.00	\$0.00	\$10.90
CCO / Channel - cleaned out	30.0	\$607.80	\$110.31	\$29.82	\$0.00	\$376.50	\$1124.43
HAUL / Hauling	10.0	\$217.90	\$94.20	\$35.70	\$0.00	\$0.00	\$347.80
UTLOC / Utility locates	0.5	\$12.35	\$0.00	\$0.00	\$0.00	\$6.62	\$18.97
2018-571 / Candy Johnson Drive Channel #1 Sub Total	41.0	\$848.95	\$204.51	\$65.52	\$0.00	\$383.12	\$1,502.09
Grand Total	41.0	\$848.95	\$204.51	\$65.52	\$0.00	\$383.12	\$1,502.09

Before



During



After





Project: Candy Johnson Drive Channel #1

Activity: Routine/ Preventive Maintenance














Project #: 2018-571

Township/SW Dist: St. Helena Island/8

Completed: February 2018

Legend

Drainage Type

-  Access Pipe
-  Bleeder Pipe
-  Channel Pipe
-  Channel
-  Stream
-  Crossline Pipe
-  Driveway Pipe
-  Lateral
-  Lateral Pipe
-  River
-  Road Pipe
-  Roadside
-  Roadside Pipe



1 inch = 210 feet

Prepared By: BC Stormwater Management Utility

Date Print: 06/25/18

File: C:\project summaries map\Candy Johnson Drive Channel #1_2018-571