



Beaufort County Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Gamecock Way Channel #1

Activity: Routine/Preventive Maintenance

Duration: 11/28/18-03/07/18

Narrative Description of Project:

Project improved 920 L.F. of drainage system. Cleaned out 920 L.F. of channel.

| 2018-536 / Gamecock Way Channel #1 | Labor Hours | Labor Cost | Equipment Cost | Material Cost | Contractor Cost | Indirect Labor | Total Cost |
|--|--------------------|-------------------|-----------------------|----------------------|------------------------|-----------------------|-------------------|
| AUDIT / Audit Project | 0.5 | \$10.90 | \$0.00 | \$0.00 | \$0.00 | \$0.00 | \$10.90 |
| CCO / Channel - cleaned out | 55.0 | \$1146.55 | \$202.62 | \$77.86 | \$0.00 | \$535.20 | \$1962.23 |
| HAUL / Hauling | 5.0 | \$111.35 | \$47.10 | \$29.77 | \$0.00 | \$72.10 | \$260.32 |
| 2018-536 / Gamecock Way Channel #1 Sub Total | 60.5 | \$1,268.80 | \$249.72 | \$107.63 | \$0.00 | \$607.30 | \$2,233.44 |
| Grand Total | 60.5 | \$1,268.80 | \$249.72 | \$107.63 | \$0.00 | \$607.30 | \$2,233.44 |

Before




During



After





Project: Gamecock Way Channel #1

Activity: Routine/ Preventive Maintenance

Project #: 2018-536

Township/SW Dist: Port Royal Island/6

Completed: March 2018

| Legend | |
|---------------|----------------|
| Drainage Type | |
| | Access Pipe |
| | Bleeder Pipe |
| | Channel Pipe |
| | Channel |
| | Stream |
| | Crossline Pipe |
| | Driveway Pipe |
| | Lateral |
| | Lateral Pipe |
| | River |
| | Road Pipe |
| | Roadside |
| | Roadside Pipe |



1 inch = 330 feet

Prepared By: BC Stormwater Management Utility
 Date Print: 06/25/18
 File: C:\project summaries map\Gamecock Way Channel #1_2018-536