



Beaufort County Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Peaches Hill Circle Channel #1

Activity: Routine/Preventive Maintenance

Duration: 02/05/18-02/06/18

Narrative Description of Project:

Project improved 2,246 L.F. of drainage system. Removed blockage from flowline. Cleaned out 2,246 L.F. of channel.

2018-576 / Peaches Hill Circle Channel #1	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.90	\$0.00	\$0.00	\$0.00	\$0.00	\$10.90
CCO / Channel - cleaned out	15.0	\$303.90	\$67.54	\$19.04	\$0.00	\$188.25	\$578.73
RB / Remove blockage from flowline	15.0	\$303.90	\$67.54	\$23.80	\$0.00	\$188.25	\$583.49
2018-576 / Peaches Hill Circle Channel #1 Sub Total	30.5	\$618.70	\$135.08	\$42.84	\$0.00	\$376.50	\$1,173.11
Grand Total	30.5	\$618.70	\$135.08	\$42.84	\$0.00	\$376.50	\$1,173.11

(Pictures Not Available)


Project: Peaches Hill Circle Channel #1

Activity: Routine/ Preventive Maintenance

Project #: 2018-576

Township/SW Dist: St. Helena Island/8

Completed: February 2018



Legend	
Drainage Type	
	Access Pipe
	Bleeder Pipe
	Channel Pipe
	Channel
	Stream
	Crossline Pipe
	Driveway Pipe
	Lateral
	Lateral Pipe
	River
	Road Pipe
	Roadside
	Roadside Pipe



1 inch = 420 feet

Prepared By: BC Stormwater Management Utility
Date Print: 07/02/18
File: C:\project summaries map\Peaches Hill Circle Channel #1 2018-576