



Beaufort County Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Pine Grove Road

Activity: Routine/Preventive Maintenance

Duration: 05/21/18-05/22/18

Narrative Description of Project:

Project improved 580 L.F. of drainage system. Cleaned out 580 L.F. of roadside ditch.

2018-612 / Pine Grove Road	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.90	\$0.00	\$0.00	\$0.00	\$0.00	\$10.90
HAUL / Hauling	20.0	\$469.75	\$135.58	\$137.76	\$0.00	\$205.45	\$948.54
RSDCL / Roadside Ditch - Cleanout	15.0	\$360.80	\$190.71	\$52.61	\$0.00	\$205.45	\$809.57
2018-612 / Pine Grove Road Sub Total	35.5	\$841.45	\$326.29	\$190.37	\$0.00	\$410.90	\$1,769.00
Grand Total	35.5	\$841.45	\$326.29	\$190.37	\$0.00	\$410.90	\$1,769.00


Before



During



(Picture Not Available)



Project: Pine Grove Road

Activity: Routine/ Preventive Maintenance

Project #: 2018-612

Township/SW Dist: Port Royal Island/6

Completed: May 2018

Legend	
Drainage Type	
	Access Pipe
	Bleeder Pipe
	Channel Pipe
	Channel
	Stream
	Crossline Pipe
	Driveway Pipe
	Lateral
	Lateral Pipe
	River
	Road Pipe
	Roadside
	Roadside Pipe



1 inch = 500 feet