



Beaufort County Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Sheldon Tree Removal- Paige Point Bluff and Big Estate Circle

Activity: Routine/Preventive Maintenance

Duration: 02/08/18-02/09/18

Narrative Description of Project:

Project improved 50 L.F. of drainage system. Removed fallen tree from workshelf and blockage from flowline by hand. Cleaned out 50 L.F. of roadside ditch.

2018-573 / Sheldon Tree Removal	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.90	\$0.00	\$0.00	\$0.00	\$0.00	\$10.90
HAUL / Hauling	11.0	\$244.97	\$103.62	\$54.74	\$0.00	\$158.62	\$561.95
RMTRW / Remove trees - Workshelf	9.0	\$200.49	\$39.43	\$16.66	\$0.00	\$128.79	\$385.37
RSDCL / Roadside Ditch - Cleanout	16.0	\$366.16	\$57.43	\$26.18	\$0.00	\$237.60	\$687.37
2018-573 / Sheldon Tree Removal Sub Total	36.5	\$822.52	\$200.48	\$97.58	\$0.00	\$525.01	\$1,645.59
Grand Total	36.5	\$822.52	\$200.48	\$97.58	\$0.00	\$525.01	\$1,645.59

(No Pictures Available)



Project: Sheldon Tree Removal - Paige Point Bluff Channel #1

Activity: Routine/ Preventive Maintenance














Project #: 2018-573

Township/SW Dist: Sheldon/5

Completed: April 2018

Legend

Drainage Type

-  Access Pipe
-  Bleeder Pipe
-  Channel Pipe
-  Channel
-  Stream
-  Crossline Pipe
-  Driveway Pipe
-  Lateral
-  Lateral Pipe
-  River
-  Road Pipe
-  Roadside
-  Roadside Pipe



1 inch = 250 feet

Prepared By: BC Stormwater Management Utility

Date Print: 10/02/18

File: C:\project summaries map\Sheldon Tree Removal- Paige Point Bluff Channel #1_2018-573