



Beaufort County Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Sheldon Washout Repairs- Jasmine Hall and Wimbee Creek Road

Activity: Routine/Preventive Maintenance

Duration: 10/04/17-04/03/18

Narrative Description of Project:

Repaired washouts.

2018-529 / Sheldon Washout Repairs	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.90	\$0.00	\$0.00	\$0.00	\$0.00	\$10.90
HAUL / Hauling	24.0	\$504.58	\$226.08	\$117.99	\$0.00	\$201.88	\$1,050.53
RPWO / Repaired Washout	28.0	\$621.38	\$181.37	\$41.76	\$0.00	\$398.76	\$1,243.27
2018-529 / Sheldon Washout Repairs Sub Total	52.5	\$1,136.86	\$407.45	\$159.75	\$0.00	\$600.64	\$2,304.69
Grand Total	52.5	\$1,136.86	\$407.45	\$159.75	\$0.00	\$600.64	\$2,304.69

Before



During

(No Picture Available)

After





Project: Sheldon Washouts Repairs-Jasmine Hall Channel

Activity: Routine/ Preventive Maintenance














Project #: 2018-529

Township/SW Dist: Sheldon/5

Completed: April 2018

Legend

Drainage Type

-  Access Pipe
-  Bleeder Pipe
-  Channel Pipe
-  Channel
-  Stream
-  Crossline Pipe
-  Driveway Pipe
-  Lateral
-  Lateral Pipe
-  River
-  Road Pipe
-  Roadside
-  Roadside Pipe



1 inch = 340 feet

Prepared By: BC Stormwater Management Utility

Date Print: 10/02/18

File: C:\project summaries map\Sheldon Washouts Repairs-Jasmine Hall Channel_2018-529



Project: Sheldon Washout Repairs- Wimbee Creek Road

Activity: Routine/ Preventive Maintenance

Project #: 2018-529

Township/SW Dist: Sheldon/5

Completed: April 2018

Legend	
	Access Pipe
	Bleeder Pipe
	Channel Pipe
	Channel
	Stream
	Crossline Pipe
	Driveway Pipe
	Lateral
	Lateral Pipe
	River
	Road Pipe
	Roadside
	Roadside Pipe



1 inch = 160 feet

Prepared By: BC Stormwater Management Utility
Date Print: 10/02/18

File: C:\project summaries map\Sheldon Washouts Repairs- Wimbee Creek Road_2018-529