



Beaufort County Public Works
Stormwater Infrastructure
Project Summary

Project Summary: To HHI Vacuum Truck
Bay Pines Drive and Leg O Mutton Road

Activity: Routine/Preventive Maintenance
Duration: 02/05/18-02/12/18

Narrative Description of Project:

Project improved 292 L.F. of drainage system. Cleaned out (3) catch basins. Jetted (1) crossline pipe and 292 L.F. of roadside pipe.

2018-311A / ToHHI Vacuum Truck	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.90	\$0.00	\$0.00	\$0.00	\$0.00	\$10.90
CBCO / Catch basin - clean out	20.0	\$445.60	\$86.80	\$69.74	\$0.00	\$286.80	\$888.94
RSPJ / Roadside Pipe - Jetted	20.0	\$445.60	\$86.80	\$77.12	\$0.00	\$286.80	\$896.32
2018-311A / ToHHI Vacuum Truck Sub Total	40.5	\$902.10	\$173.60	\$146.86	\$0.00	\$573.60	\$1,796.16
Grand Total	40.5	\$902.10	\$173.60	\$146.86	\$0.00	\$573.60	\$1,796.16

Before



During



After





Project: ToHHI Vacuum Truck-Bay Pines Drive Map #1

Activity: Routine/ Preventive Maintenance

Project #: 2018-311A

Township/SW Dist: ToHHI/3

Completed: February 2018

Legend	
Drainage Type	
	Access Pipe
	Bleeder Pipe
	Channel Pipe
	Channel
	Stream
	Crossline Pipe
	Driveway Pipe
	Lateral
	Lateral Pipe
	River
	Road Pipe
	Roadside
	Roadside Pipe

0 15 30 60 90 120 Feet

1 inch = 67 feet

Prepared By: BC Stormwater Management Utility

Date Print: 10/16/18

File: C:\project summaries map\ToHHI Vac Truck- Bay Pines Drive Map #1_2018A-311



Project: ToHHI
 Vacuum Truck-
 Leg O Mutton Road
 Map #2

Activity: Routine/
 Preventive
 Maintenance

Project #:
 2018-311A

Township/SW Dist:
 ToHHI/3

Completed:
 February 2018

Legend	
Drainage Type	
	Access Pipe
	Bleeder Pipe
	Channel Pipe
	Channel
	Stream
	Crossline Pipe
	Driveway Pipe
	Lateral
	Lateral Pipe
	River
	Road Pipe
	Roadside
	Roadside Pipe



1 inch = 210 feet