



**Beaufort County Public Works**  
**Stormwater Infrastructure**  
*Project Summary*

**Project Summary:** Laurel Street W

**Activity:** Routine/Preventive Maintenance

**Duration:** 10/18/17-10/24/17

**Narrative Description of Project:**

Project improved 1,276 L.F. of drainage system. Cleaned out 1,276 L.F. of roadside ditch.

2018-537 / Laurel Street W	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.90	\$0.00	\$0.00	\$0.00	\$0.00	\$10.90
HAUL / Hauling	23.0	\$512.21	\$216.66	\$60.20	\$0.00	\$331.66	\$1,120.73
RSDCL / Roadside Ditch - Cleanout	35.0	\$797.95	\$227.39	\$38.06	\$0.00	\$517.60	\$1,580.99
UTLOC / Utility locates	1.0	\$24.70	\$0.00	\$0.00	\$0.00	\$13.23	\$37.93
2018-537 / Laurel Street W Sub Total	59.5	\$1,345.76	\$444.05	\$98.26	\$0.00	\$862.49	\$2,750.55
<b>Grand Total</b>	<b>59.5</b>	<b>\$1,345.76</b>	<b>\$444.05</b>	<b>\$98.26</b>	<b>\$0.00</b>	<b>\$862.49</b>	<b>\$2,750.55</b>

**Before**



**During**



**After**







Project: Laurel Street W

Activity: Routine/ Preventive Maintenance














Project #: 2018-537

Township/SW Dist: Port Royal Island/6

Completed: October 2017

**Legend**

**Drainage Type**

-  Access Pipe
-  Bleeder Pipe
-  Channel Pipe
-  Channel
-  Stream
-  Crossline Pipe
-  Driveway Pipe
-  Lateral
-  Lateral Pipe
-  River
-  Road Pipe
-  Roadside
-  Roadside Pipe



**1 inch = 130 feet**

Prepared By: BC Stormwater Management Utility  
Date Print: 04/11/18  
File: C:\project summaries map\Laurel Street W\_2018-537